

# Town of Hanover

## Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
1/8/1987		HFD #2	25				
6/18/1987		HFD #2	1.3				
11/27/1990		HFD #2	ND	ND	ND	ND	ND
7/19/1991		HFD #2	ND	ND	ND	ND	ND
9/17/1992		HFD #2	66.5	ND	54.87	10.7	1
9/14/1993		HFD #2	38.3	ND	19.2	13.2	5.9
8/9/1994		HFD #2	28.5	ND	19	7.1	2.4
8/14/1995		HFD #2	9.1	5.9	ND	0.6	2.6
3/25/1996		HFD #2	9.4	7.3	ND	ND	2.1
9/17/1996		HFD #2	33.1	15	8.3	3.3	6.5
12/17/1996		HFD #2	9.7	6.6	ND	ND	3.1
2/24/1997		HFD #2	13.2	5.6	2.3	1.5	3.8
6/2/1997		HFD #2	12.1	7.7	ND	0.9	3.5
8/25/1997		HFD #2	5.9	3.2	ND	0.5	2.2
11/17/1997		HFD #2	7.2	4.5	ND	0.7	2
1/2/1998		HFD #2	51.4	1.4	36	11.9	2.1
6/8/1998		HFD #2	14.4	9.4	ND	1.2	3.8
9/15/1998		HFD #2	6.9	3.1	0.7	0.8	2.3
11/10/1998		HFD #2	19.5	9	1.3	2.5	6.7
2/16/1999		HFD #2	13.5	7.2	0.7	1.4	4.2
4/2/1999		HFD #2	12	6.7	ND	1	4.3
7/16/1999		HFD #2	6	3.5	ND	0.6	1.9
10/19/1999		HFD #2	10.1	5.6	0.7	0.9	2.9
3/15/2000		HFD #2	50.7	ND	39.1	9.8	1.8
6/13/2000		HFD #2	34.3	6.7	17.4	6.1	4.1
9/21/2000		HFD #2	ND	ND	ND	ND	ND
11/14/2000		HFD #2	ND	ND	ND	ND	ND
3/8/2001		HFD #2	11.3	6.5	ND	1.1	3.7
5/11/2001		HFD #2	7.8	3	ND	1.2	3.6
8/28/2001		HFD #2	18.7	11.8	ND	1.5	5.4
10/23/2001		HFD #2	17.8	8.6	0.6	2.1	6.5
2/6/2002		HFD #2	16.1	9.3	ND	1.3	5.5
3/4/2002		70 Ponderosa Drive	80	ND	55.3	20.1	4.6

# Town of Hanover

## Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
3/4/2002		925 Circuit St - HFD #3	61.3	1.3	41.5	14.4	4.1
3/4/2002		Hanover Mall Office	85.8	ND	59.3	21.6	4.9
3/4/2002		HFD #1	74.3	ND	51.7	18.6	4
3/25/2002		HFD #2	7.1	3.3	ND	0.9	2.9
3/25/2002		HFD #6	36.4	13.3	8.4	5.3	9.4
3/25/2002		Myettes Country Store	9.3	4.4	ND	1.2	3.7
3/25/2002		Town Hall	37.8	6.3	17.6	7.2	6.7
5/7/2002		70 Ponderosa Drive	110	0.6	83.2	22.2	4.4
5/7/2002		925 Circuit St - HFD #3	48	2.5	32.7	8.9	3.9
5/7/2002		Hanover Mall Office	133.1	ND	104	24.9	4.2
5/7/2002		HFD #1	84.6	ND	62.3	18.5	3.8
5/7/2002		HFD #2	12.6	6.6	ND	1.3	4.7
5/7/2002		HFD #6	38.9	9	14.6	6.4	8.9
5/7/2002		Myettes Country Store	10	4.3	ND	1.5	4.2
5/7/2002		Town Hall	30.8	3.5	17	6	4.3
9/10/2002		70 Ponderosa Drive	72.5	1.2	37.8	23.4	10.1
9/10/2002		925 Circuit St - HFD #3	36.4	3.4	17.4	9.6	6
9/10/2002		HFD #2	10.7	5.6	ND	1.1	4
9/10/2002		HFD #6	34.1	19	1.2	3.2	10.7
11/26/2002		70 Ponderosa Drive	87.1	ND	67.5	16.6	3
11/26/2002		925 Circuit St - HFD #3	56.5	3.6	39.5	9.9	3.5
11/26/2002		HFD #2	7.4	3.4	ND	1	3
11/26/2002		HFD #6	34.8	10.1	13.7	5	6
3/4/2003		70 Ponderosa Drive	66.1	ND	44	17.5	4.6
3/4/2003		925 Circuit St - HFD #3	29.6	ND	20.1	7.4	2.1
3/4/2003		HFD #2	21.7	ND	16.6	4.3	0.8
3/4/2003		HFD #6	24.1	5.5	10.1	4.6	3.9
4/15/2003		70 Ponderosa Drive	68.8	ND	50.2	15.4	3.2
4/15/2003		925 Circuit St - HFD #3	40.6	ND	29.8	8.9	1.9
4/15/2003		HFD #2	6.8	3.2	ND	0.8	2.8
4/15/2003		HFD #6	21.2	11.6	1.4	2	6.2
7/1/2003		70 Ponderosa Drive	55.2	0.8	35.9	14.4	4.1
7/1/2003		925 Circuit St - HFD #3	17.7	2.1	11.2	2.5	1.9
7/1/2003		HFD #2	7.6	3.7	ND	0.8	3.1

# Town of Hanover

## Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
7/1/2003		HFD #6	30.2	13.2	3.4	3.5	10.1
10/14/2003		70 Ponderosa Drive	64.7	ND	37.9	20.1	6.7
10/14/2003		925 Circuit St - HFD #3	59.6	1.2	33.2	18.2	7
10/14/2003		HFD #2	ND	ND	ND	ND	ND
10/14/2003		HFD #6	41.4	9.1	14.9	9.7	7.7
3/2/2004		70 Ponderosa Drive	66	ND	37.4	21.5	7.1
3/2/2004		925 Circuit St - HFD #3	40.7	6.6	15.1	10.7	8.3
3/2/2004		HFD #1	54.5	ND	29.7	18.5	6.3
3/2/2004		HFD #2	37.8	3.2	14.7	12.3	7.6
3/2/2004		HFD #6	53	0.8	28.4	17.6	6.2
3/15/2004		Cedar School	55.5	ND	34.5	15.8	5.2
3/16/2004		640 King St	35.2	3.8	14.3	10.6	6.5
6/2/2004		70 Ponderosa Drive	103	1.4	71.3	23.4	6.4
6/2/2004		925 Circuit St - HFD #3	79.1	2.5	51.5	18.5	6.6
6/2/2004		Bleeder - King St at Hanson Line	40.2	17.2	6.9	6.2	9.9
8/17/2004		70 Ponderosa Drive	63.3	2.1	31.7	20.4	9.1
8/17/2004		925 Circuit St - HFD #3	50.3	2.9	22.9	16	8.5
8/17/2004		Bleeder - King St at Hanson Line	48.5	19.3	7.7	8.8	12.7
10/19/2004		70 Ponderosa Drive	70.6	1.3	42.5	20	6.8
10/19/2004		925 Circuit St - HFD #3	65.4	4	34.4	18.6	8.4
10/19/2004		Bleeder - King St at Hanson Line	37.3	10.5	9.4	8	9.4
2/15/2005		Beal WTP	3.9	1.3	ND	1	1.6
2/15/2005		Broadway WTP	11	ND	7.7	3.3	1
2/15/2005		Pond St WTP	25.4	ND	18.5	5.4	1.5
3/15/2005		640 King St	29.2	8.9	3.7	5.9	10.7
3/15/2005		70 Ponderosa Drive	34.7	1.1	16.7	10.9	6
3/15/2005		925 Circuit St - HFD #3	30	0.7	16.7	8.7	3.9
5/3/2005		640 King St	41.5	10.5	12.2	8.7	10.1
5/3/2005		70 Ponderosa Drive	45.9	0.8	27.9	12.4	4.8
5/3/2005		925 Circuit St - HFD #3	41.2	1.7	25.5	9.9	4.1
7/12/2005		640 King St	39.7	8.4	12.8	9.1	9.4
7/12/2005		70 Ponderosa Drive	63.7	ND	43.1	16.1	4.5
7/12/2005		925 Circuit St - HFD #3	58.2	0.8	35.4	16.3	5.7
12/5/2005		640 King St	ND	ND	ND	ND	ND

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
12/5/2005		70 Ponderosa Drive	47.5	0.9	29.3	12.9	4.4
12/5/2005		925 Circuit St - HFD #3	39.5	1.3	22.7	11.2	4.3
2/7/2006		70 Ponderosa Drive	37.2	0.5	22.4	10.6	3.7
2/7/2006		925 Circuit St - HFD #3	35.6	0.7	22.1	9.6	3.2
2/7/2006		Bleeder at Hanson Line	ND	ND	ND	ND	ND
5/1/2006		640 King St	ND	ND	ND	ND	ND
5/1/2006		70 Ponderosa Drive	32.2	ND	17.8	10.4	4
5/1/2006		925 Circuit St - HFD #3	26.7	ND	16.9	7.7	2.1
8/14/2006		70 Ponderosa Drive	72.6	1.3	45.7	19	6.6
8/14/2006		925 Circuit St - HFD #3	39.6	0.7	24.4	10.8	3.7
8/14/2006		King St	37.5	13.6	5.2	6.7	12
11/29/2006		640 King St	30	8.4	7.8	6.3	7.5
11/29/2006		70 Ponderosa Drive	58.5	0.9	38.8	14.5	4.3
11/29/2006		925 Circuit St - HFD #3	45.6	1.2	28.4	12.2	3.8
1/4/2007		640 King St	31.3	6.3	11.8	6.6	6.6
1/4/2007		70 Ponderosa Drive	56.9	0.7	40.7	12.2	3.3
1/4/2007		925 Circuit St - HFD #3	52	ND	39.1	10.5	2.4
4/5/2007		640 King St	33.6	8.5	8.6	7.1	9.4
4/5/2007		70 Ponderosa Drive	59.8	1.2	36.4	15.8	6.4
4/5/2007		925 Circuit St - HFD #3	57.9	3.2	32.3	14.8	7.6
7/10/2007		640 King St	25.4	3.9	9.5	6.2	5.8
7/10/2007		70 Ponderosa Drive	44.9	ND	35.4	8	1.5
7/10/2007		925 Circuit St - HFD #3	33.8	ND	24.1	7.4	2.3
8/21/2007		149 King St	29.7	6.9	3.8	7.3	11.7
8/21/2007		19 Rockland St	45.8	2.4	15.6	14.9	12.9
8/21/2007		219 Winter Street	23.3	4.7	3.7	6.1	8.8
8/21/2007		640 King St	41.4	9.3	10.3	9.5	12.3
8/21/2007		70 Ponderosa Drive	62.4	2.7	25.5	20.6	13.6
8/21/2007		925 Circuit St - HFD #3	46.6	2.3	20.1	14.4	9.8
8/21/2007		Main St HFD #1	63.4	2	28.4	21.1	11.9
8/21/2007		Merchants Row Mall	79.9	2.5	36.7	26.2	14.5
8/21/2007		Webster St	74	2.4	32.4	24.8	14.4
10/2/2007		640 King St	28.2	8.1	6.2	5.8	8.1
10/2/2007		70 Ponderosa Drive	43.9	1.4	23	12.8	6.7

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
10/2/2007		925 Circuit St - HFD #3	32.1	3.4	12	9.1	7.6
1/22/2008		640 King St	22.2	6.8	4.1	4.5	6.8
1/22/2008		70 Ponderosa Drive	38.2	ND	25.1	10.2	2.9
1/22/2008		925 Circuit St - HFD #3	36	3.5	16.7	9.3	6.5
4/8/2008		640 King St	31.1	65.6	10.3	6.6	7.6
4/8/2008		70 Ponderosa Drive	48.7	0.7	34.8	10	3.2
4/8/2008		925 Circuit St - HFD #3	36.5	1.6	24.1	7.2	3.6
7/15/2008		640 King St	52.1	3.2	29.2	12.4	7.3
7/15/2008		70 Ponderosa Drive	73.4	ND	59.8	11.8	1.8
7/15/2008		925 Circuit St - HFD #3	64.5	ND	53.9	9.3	1.3
10/28/2008		640 King St	23.7	3.5	10	5.6	4.6
10/28/2008		70 Ponderosa Drive	56.4	1.7	36.5	13.8	4.4
10/28/2008		925 Circuit St - HFD #3	44.5	1.5	27.3	11.2	4.5
2/7/2009		640 King St	38.4	7	13	9	9.4
2/7/2009		70 Ponderosa Drive	48.1	0.9	29.1	13	5.1
2/7/2009		925 Circuit St - HFD #3	41	2.4	23	10.2	5.4
6/17/2009		640 King St	39.3	6.2	14.8	9	9.3
6/17/2009		70 Ponderosa Drive	77.1	0.7	48.2	21.4	6.8
6/17/2009		925 Circuit St - HFD #3	58.4	0.8	39.1	14.2	4.3
7/28/2009		640 King St	35.3	4.2	14.1	9.2	7.8
7/28/2009		70 Ponderosa Drive	108	ND	77.5	25	5.3
7/28/2009		925 Circuit St - HFD #3	75.9	1.2	51.7	17.5	5.5
11/30/2009		640 King St	28.4	3.3	11.1	7.8	6.2
11/30/2009		70 Ponderosa Drive	62.2	ND	46.9	12.3	3
11/30/2009		925 Circuit St - HFD #3	39.9	0.7	28.5	8	2.7
2/23/2010		640 King St	28.7	4.7	9	7	8
2/23/2010		70 Ponderosa Drive	41.4	0.8	21	13.1	6.5
2/23/2010		925 Circuit St - HFD #3	46.4	2	23.5	13.5	7.4
6/8/2010		640 King St	36.4	7.9	8.4	9.1	11
6/8/2010		70 Ponderosa Drive	84.5	1	49.8	25.4	8.3
6/8/2010		925 Circuit St - HFD #3	50.1	2.9	22.3	15.2	9.7
8/10/2010		640 King St	42.6	8.3	12.6	10.5	11.2
8/10/2010		70 Ponderosa Drive	68.7	2.6	29	22.4	14.7
8/10/2010		925 Circuit St - HFD #3	72.6	4.7	35.8	19.1	13

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
11/2/2010		640 King St	41.2	6.8	12.7	11	10.7
11/2/2010		70 Ponderosa Drive	93.6	0.8	61.4	24	7.4
11/2/2010		925 Circuit St - HFD #3	80.3	2.3	47.3	21.7	9
3/22/2011		640 King St	43.6	5.6	15.1	11.3	11.6
3/22/2011		70 Ponderosa Drive	83.5	10.1	19.1	27	27.3
3/22/2011		925 Circuit St - HFD #3	76	5.6	29.8	22.8	17.8
6/15/2011		640 King St	40.3	5.7	14	10.5	10.1
6/15/2011		925 Circuit St - HFD #3	80.2	2.8	42.2	23.2	12
6/15/2011		70 Ponderosa Drive	104	1.4	52.9	33.8	16.3
8/23/2011		640 King St	18.4	2	5.3	6.2	4.9
8/23/2011		925 Circuit St - HFD #3	71.2	3.9	35.4	20.8	11.1
8/23/2011		70 Ponderosa Drive	108	2	57.9	32.9	15.4
12/19/2011		640 King St	39.8	5.9	11.6	11.1	11.2
12/19/2011		925 Circuit St - HFD #3	89.8	4.3	47.8	24.8	12.9
12/19/2011		70 Ponderosa Drive	120	1.4	73.7	33.4	11.3
3/13/2012		640 King St	40.6	6.3	14.4	10.7	9.2
3/13/2012		70 Ponderosa Drive	69.4	2.9	30.1	22.7	13.7
3/13/2012		925 Circuit St - HFD #3	67.6	2.9	28.2	22.7	13.8
6/5/2012		640 King St	67.5	3.8	35.6	18.5	9.6
6/5/2012		70 Ponderosa Drive	109	0.7	63	33.9	11
6/5/2012		925 Circuit St - HFD #3	106	1	60.8	32.8	10.9
9/18/2012		640 King St	31.5	2.6	12.9	9.6	6.4
9/18/2012		70 Ponderosa Drive	104	1.5	62.7	29.7	10.5
9/18/2012		925 Circuit St - HFD #3	92.2	2.2	53.6	26.2	10.2
11/6/2012		640 King St	37.1	0.8	20.2	12.2	3.9
11/6/2012		70 Ponderosa Drive	93.2	1	54.9	26.7	10.6
11/6/2012		925 Circuit St - HFD #3	77	3.1	42.2	21.1	10.6
3/26/2013		640 King St	13.6	1.1	2.5	5.3	4.7
3/26/2013		70 Ponderosa Drive	85.5	6.9	22.7	29.3	26.6
3/26/2013		925 Circuit St - HFD #3	46.9	11.8	6.8	11.65	16.7
5/6/2013		640 King St	36.4	2.9	12.9	12.1	8.5
5/6/2013		70 Ponderosa Drive	84.6	2.1	35.3	29.1	17.5
5/6/2013		925 Circuit St - HFD #3	60.2	5.8	19.9	18.9	15.6
9/17/2013		640 King St	45.9	3.2	19.9	13.9	8.9

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
9/17/2013		70 Ponderosa Drive	168	2.6	95.4	49.5	20.4
9/17/2013		925 Circuit St - HFD #3	108	5.1	56.8	30.7	15.4
12/3/2013		2055 Washington Street - Computer Center	51.6	1.9	18.2	18.5	13
12/3/2013		33 Rockland St - Hanover Fitness	74.2	2.8	36.4	22.7	12.3
12/3/2013		70 Ponderosa Drive	79.4	6.7	25.7	24.8	22.2
12/3/2013		925 Circuit St - HFD #3	67.8	5.4	26.5	21	14.9
3/18/2014		2055 Washington Street - Computer Center	26.3	3.2	5.3	8	9.8
3/18/2014		33 Rockland St - Hanover Fitness	74.3	1.8	43.3	19.1	10.1
3/18/2014		70 Ponderosa Drive	51	6.3	14.5	14	16.1
3/18/2014		925 Circuit St - HFD #3	39.7	6.6	12.4	9.5	11.2
6/10/2014		2055 Washington Street - Computer Center	84.2	2.8	29.5	31.3	20.6
6/10/2014		33 Rockland St - Hanover Fitness	40.3	0.9	22.8	11	5.6
6/10/2014		925 Circuit St - HFD #3	46.2	11.3	10.3	11	13.6
6/17/2014		70 Ponderosa Drive	78	4.2	26.4	27.5	19.9
9/23/2014		2055 Washington Street - Computer Center	44.5	6.6	10.4	13.1	14.4
9/23/2014		33 Rockland St - Hanover Fitness	80.5	nd	57.2	18	5.3
9/23/2014		70 Ponderosa Drive	73.4	6.6	19.4	24	23.4
9/23/2014		925 Circuit St - HFD #3	53.3	7.4	15.2	15.8	14.9
12/30/2014		2055 Washington Street - Computer Center	77.7	1.7	39.1	24.5	12.4
12/30/2014		33 Rockland St - Hanover Fitness	57	2.2	26.8	16.3	11.7
12/30/2014		70 Ponderosa Drive	86.3	2.7	40.4	27.3	15.9
12/30/2014		925 Circuit St - HFD #3	72.4	3.3	33.4	21.7	14
3/3/2015		2055 Washington Street - Computer Center	30.6	5.6	3.6	8.5	12.9
3/3/2015		33 Rockland St - Hanover Fitness	7.9	0.6	46.7	25	80.2
3/3/2015		70 Ponderosa Drive	80	9.3	16.9	22.9	30.9
3/3/2015		925 Circuit St - HFD #3	77.2	7	28.9	22.5	18.8
3/17/2015		Pond St WTP Clearwell	4.6	1	0.8	1.2	1.6
3/17/2015		Pond St WTP Finished Water	12	3.2	1.3	2.8	4.7
6/5/2015		2055 Washington Street - Computer Center	65.7	1.8	24.5	23.5	15.9
6/5/2015		33 Rockland St - Hanover Fitness	76.6	0.5	57.2	14.9	4
6/5/2015		70 Ponderosa Drive	97.5	4.9	30.9	35	26.7
6/5/2015		925 Circuit St - HFD #3	42.1	6.6	8	11.9	15.6
8/4/2015	12:00	58 Rockland St	7.1	1.1	1.1	1.9	3
9/10/2015		2055 Washington Street - Computer Center	46.6	4.2	9.6	15.8	17

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
9/10/2015		33 Rockland St - Hanover Fitness	8	1.3	1.5	2	3.2
9/10/2015		70 Ponderosa Drive	82.7	8.4	18.5	27.2	28.6
9/10/2015		925 Circuit St - HFD #3	34.8	6.2	6.4	9.4	12.8
12/1/2015		2055 Washington Street - Computer Center	45.6	1.3	17.8	16.6	9.9
12/1/2015		33 Rockland St - Hanover Fitness	33.1	3.5	7	10.6	12
12/1/2015		70 Ponderosa Drive	58.7	6.4	14.6	19.3	18.4
12/1/2015		925 Circuit St - HFD #3	40.9	14.2	4	7.7	15
12/1/2015		Beal WTP Finished Water	4.7	2.2	ND	0.6	1.9
12/1/2015		Broadway WTP Finished Water	1.9	ND	0.7	0.6	0.6
12/1/2015		Pond St WTP Finished Water	23.7	ND	8.5	10.3	4.9
3/1/2016		2055 Washington Street - Computer Center	68.6	4.7	16.6	25	22.3
3/1/2016		33 Rockland St - Hanover Fitness	23.4	3.1	4.4	7	8.9
3/1/2016		70 Ponderosa Drive	64.8	8.8	12.9	20.1	23
3/1/2016		925 Circuit St - HFD #3	36.7	13.3	2.9	7.6	12.9
6/7/2016		2055 Washington Street - Computer Center	9	4.3	ND	1.1	3.6
6/7/2016		33 Rockland St - Hanover Fitness	38.3	3.5	9.65	12.4	12.8
6/7/2016		70 Ponderosa Drive	83.6	2.8	27.5	32.6	20.7
6/7/2016		925 Circuit St - HFD #3	51.2	8.8	10.2	14.3	17.9
9/7/2016		2055 Washington Street - Computer Center	21	13.5	ND	1.7	5.8
9/7/2016		33 Rockland St - Hanover Fitness	47	5.7	9.1	14.5	17.74
9/7/2016		70 Ponderosa Drive	81.6	9.6	12.8	27.2	32
9/7/2016		925 Circuit St - HFD #3	51.8	14.5	6.1	10.1	21.1
12/9/2016		2055 Washington Street - Computer Center	46.5	12.5	6.2	11.4	16.6
12/9/2016		33 Rockland St - Hanover Fitness	29.4	4.2	4.4	8.5	12.3
12/9/2016		70 Ponderosa Drive	72.8	13.4	13.5	20.9	25
12/9/2016		925 Circuit St - HFD #3	38.1	13.2	3	7.3	14.6
3/7/2017		2055 Washington Street - Computer Center	20.6	9.8	1.4	3.1	6.3
3/7/2017		33 Rockland St - Hanover Fitness	26.7	3.5	5.4	8.1	9.7
3/7/2017		70 Ponderosa Drive	46.8	1.9	14.2	17.7	13
3/7/2017		925 Circuit St - HFD #3	41.3	10.2	6.9	10.4	13.8
6/7/2017		2060 Washington Street - Prime Infinity	9.5	4.5	0.5	1.4	3.1
6/7/2017		33 Rockland St - Hanover Fitness	6.1	3.2	ND	0.8	2.1
6/7/2017		70 Ponderosa Drive	94.9	1.9	39.8	34.3	18.9
6/7/2017		925 Circuit St - HFD #3	74.2	4.8	23.2	27.6	18.6



## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
9/6/2017		2060 Washington Street - Prime Infinity	7.7	4	ND	0.8	2.9
9/6/2017		33 Rockland St - Hanover Fitness	17.6	11.5	ND	1.3	4.8
9/6/2017		70 Ponderosa Drive	88	9.2	15	29	34.9
9/6/2017		925 Circuit St - HFD #3	51.4	14.3	6.6	11.6	18.9
12/6/2017		2060 Washington Street - Prime Infinity	70	3.1	36	20.9	10.1
12/6/2017		33 Rockland St - Hanover Fitness	22	2.4	6.2	6.1	7
12/6/2017		70 Ponderosa Drive	59	3.9	26.7	17.9	10.9
12/6/2017		925 Circuit St - HFD #3	48	5	19.4	14	9.8
3/7/2018		2060 Washington Street - Prime Infinity	56	1.8	19.6	20.8	14.2
3/7/2018		33 Rockland St - Hanover Fitness	21	4.1	3.8	5.8	7.6
3/7/2018		70 Ponderosa Drive	51	1.9	17	18.8	13.1
3/7/2018		925 Circuit St - HFD #3	40	4.1	10.3	12.6	13.3
6/6/2018		2060 Washington Street - Prime Infinity	103	1.4	43.5	39.2	18.8
6/6/2018		70 Ponderosa Drive	93	2.2	36	35.5	19.6
6/6/2018		925 Circuit St - HFD #3	98	1.4	38.4	38.5	19.9
6/7/2018		33 Rockland St - Hanover Fitness	72	2.8	25.9	27	16.7
9/6/2018		2060 Washington Street - Prime Infinity	104	8	23.4	36.1	36.8
9/6/2018		33 Rockland St - Hanover Fitness	103	7.5	23.7	35.6	36.6
9/6/2018		70 Ponderosa Drive	102	7.2	24	35.4	35.7
9/6/2018		925 Circuit St - HFD #3	103	7.4	24.1	35.9	35.9
9/13/2018	9:30	2060 Washington Street - Prime Infinity	73	5.8	13.4	24.6	29
9/13/2018	10:50	24 Rockland St - 1A	13	1	3.4	3.9	4.4
9/13/2018	9:20	70 Ponderosa Drive	137	0.7	91.7	34.8	9.8
9/13/2018	9:44	925 Circuit St - HFD #3	127	0.7	83.8	33.6	9.1
12/4/2018		2060 Washington Street - Prime Infinity	73	1	36	25	10.8
12/4/2018		24 Rockland St - 8	13	0.8	3.5	4.3	4.5
12/4/2018		70 Ponderosa Drive	117	3.6	60.7	35.5	17.2
12/4/2018		925 Circuit St - HFD #3	107	3.3	59	30.4	14.1
1/18/2019	8:40	25 Jay's Lane	32	0.7	10.7	12.5	7.9
1/18/2019	8:50	Hydrant across from 25 Jay's Lane	32	0.7	10.8	12.4	7.6
1/25/2019	12:57	349 Silver St - Hydrant 30-012	32	1	9.1	12.4	9.3
1/25/2019	12:37	211 Silver St - Hydrant 38-002	26	7.6	3.2	5.7	9.7
1/25/2019	12:47	290 Silver St - Hydrant 38-004	33	1	9.5	12.8	9.6
1/25/2019	12:22	65 Silver St - Hydrant 47-001	23	5.9	3	5.4	8.7

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total			Bromodichloromet hane	Dibromochloromet hane
			Trihalomethanes (TTHM's)	Bromoform	Chloroform		
1/31/2019	11:41	2060 Washington Street - Prime Infinity	42	2	10.8	15.4	13.4
1/31/2019	11:00	McDonalds 1392 Washington St	39	1.8	10.4	14.5	12.1
1/31/2019	11:14	Sullivan Tire 1792 Washington St	31	1.6	6.8	11.5	10.7
1/31/2019	11:28	Valvoline 1988 Washington St	31	1.6	6.7	11.8	10.5
2/1/2019	8:00	168 Dwelley Ave (Kitchen Sink)	75	2.5	27.7	27	18.2
2/1/2019	7:55	168 Dwelley Ave (Post Brita Filter)	11	ND	4.8	4	2.2
3/5/2019		2060 Washington Street - Prime Infinity	22	1.4	6.7	7.8	6.4
3/5/2019		24 Rockland St - 8	25	4.1	3.7	7.2	9.7
3/5/2019		70 Ponderosa Drive	52	3.7	14.7	17.8	15.9
3/5/2019		925 Circuit St - HFD #3	37	4.8	8.9	11.2	11.9
3/19/2019	7:10	1558 Broadway (Brita filter)	15	8.2	0.5	1.5	4.3
3/19/2019	7:10	1558 Broadway (kitchen sink)	33	17.6	1.3	3.8	10.4
3/19/2019	8:45	94 Old Bridge Road (Hydrant 58-100)	34	21.2	0.7	2.6	9.1
3/19/2019	9:33	233 Curtis Mill Lane	49	2.2	14.8	17	14.6
4/9/2019	10:10	73 Phillips St	73	3.3	24	25.3	20.1
4/9/2019	9:47	55 Tower Hill Drive	49	1.7	14.7	17.4	14.9
4/22/2019	10:19	37 Phillips St (post Brita)	8.6	ND	3.7	0.6	ND
4/22/2019	10:49	Pond St WTP - Finished Water	21	0.8	5.1	8.3	6.3
4/22/2019	11:08	Beal WTP - Finished Water	14	8.3	ND	1.2	4.5
4/22/2019	11:37	Broadway WTP - Finished Water	7.4	0.9	1.9	1.9	2.8
5/10/2019	10:03	141 Tecumseh Dr	45	15.1	4.9	9.2	15.9
5/23/2019	14:05	48 Waterford Dr	37	18.3	2.2	5	11.4
6/4/2019		2060 Washington Street - Prime Infinity	72	ND	39.6	23.6	9
6/4/2019		24 Rockland St - 8	27	0.6	10	9.7	10
6/4/2019		70 Ponderosa Drive	80	1.1	40.6	26.5	11.3
6/4/2019		925 Circuit St - HFD #3	53	7	16.5	15.5	14.1
7/30/2019	9:15	248 Larchmont Lane	122	1.1	74.1	36.7	10.3
7/30/2019	9:15	248 Larchmont Lane - (Post Brita)	13	ND	8	3.5	1.1
7/30/2019	9:35	234 Curtis Mill Lane	82	ND	57.5	20.5	4.4
7/30/2019	8:15	539 Water Street	25	13.8	0.6	2.4	8.1
7/30/2019	8:15	539 Water Street - (Post Brita)	11	6	0.9	1.4	2.9
7/30/2019	8:45	1215 Webster Street	130	1.3	82.4	36	10.1
7/30/2019	8:45	1215 Webster Street - (Post Brita)	ND	ND	ND	ND	ND

## Town of Hanover

### Total Trihalomethane Test Results (1987-present)

Date	Time	Location	Total Trihalomethanes (TTHM's)	Bromoform	Chloroform	Bromodichloromet hane	Dibromochloromet hane
------	------	----------	--------------------------------------	-----------	------------	--------------------------	--------------------------

All test results are ug/l (micrograms per liter) which is the same as ppb (parts per billion)  
ND means "Not Detected"

All tests were performed by laboratories certified by the Massachusetts Department of Environmental Protection

Note: Standards for Total Trihalomethanes (TTHM's) have changed over the years. The current federal standard is less than 80 parts per billion as a locational running average. What this means is that at each site, the average result over the past four quarters must be less than 80 parts per billion.